F17 THE UNDER CC DOCKET 94-102

1700 G Straigh NSV • Suda 900 Maramar D. 19264 おい かりめ キャメキス 得到額も

DUDICET FILE COPY ORIGINAL



RECEIVED

JUN 27 2002

45 garage 100 Francisco y contract

Stranger and

San San Land Control of the

This was being the 1- -----

A SAME AND BOOK

CHRISTINA Alamada Emport

The Control

5-16

St. and Committee Sty.

Some of applican

on inventory Latter of materials Casing of an Camma time

> There is a property Fr & Fashington Committee

The state of the state

Done Johnson Te mai sis

> 金属 医乳色病病病 Remarks Facility

> > and the second

to the second second

数性 (14) (14) (14) (14)

June 26, 2002

Mindy Littell Attorney Policy Division Wireless Telecommunications Bureau Federal Communications Commission 445 12th Street, SW Washington, DC 20554

Dear Mindy,

Please find the Public Service Answering Point (PSAP) report you requested attached. The report was generated from the TTSI (TTY Technical Standards Implementation) Incubator Test database on June 6, 2002. The database consists of manually scored test results from random TTY user calls to various PSAPs communicating in the TTY mode. The TTY users were not under the control of the TTSI and, in most cases, results were voluntarily submitted to the TTSI for scoring. The PSAP report was automatically generated from the active records in the database.

The purpose of the TTSI testing program is to help identify issues for discussion and potential resolution by the industry. The testing is limited in scope and intended as a preliminary tool to identify issues. The testing does not certify compliance or noncompliance for any specific handset, TTY device or PSAP equipment (hardware or software). The PSAP testing results are not automated. Accordingly, neither ATIS, the TTSI Incubator, or any of their respective members or participants, make any representations or warranties regarding the accuracy of the data or the application of such date to any specific handset, TTY device or PSAP equipment (hardware or software).

Should the Commission determine there is a need to further distribute this report, we request that the above explanation of the testing and its purpose and limitations be included.

If you have any questions regarding the report, please contact me at 630-972-1454. If you have any questions regarding our distribution request, please contact Megan Campbell, ATIS General Counsel, at 202-434-8847.

Sincerely,

James L. Turner **Technical Coordinator**

Attachment

No. of Copies rec'd List ABCDE

KIND OF BUILDING

Section 1

TTSI PSAP Test Report

June, 02 (report will be updated monthly while testing continues)

This report is comprised of the entire active PSAP test records in the TTY database. It is grouped by destination Device. A destination device is a unique number representing a PSAP model. Some PSAPs can have more than one destination device due to multiple locations of the device or differing levels of the PSAP. Each entry under a destination device represents the results of a single test with the uplink (Transmit) and downlink (Receive) TCER (Total Character Error Rate) percentage. The summary is the average of all the test ran on the PSAP device.

Destination Device 100		
Destination Device 100		
Test Configuration Rate	Uplink Error Rate	Downlink Error
Landline to PSAP	0	0
Landine to PSAP		
Landline to PSAP	0.9	0.09
Mobile to PSAP	0	0
Mobile to PSAP	0	0
Summary for 'Destination Device Under	Test' = 100 (4 detail records)	
Avg Landline Average 0.45 0.45 Mobile TTY Average 0.0 0.0	0.23	0.023
Destination Device 101		
Test Configuration	Uplink Error Rate	Downlink Error
Rate		
Landline to PSAP	0.08	0
Landline to PSAP	0	0
Mobile to PSAP	0	4
Mobile to PSAP	0	4
Mobile to PSAP	0	9

Summary for 'Destination Device Under Test' = 101 (10 detail records)

0

0

0

0

0.03

0.011

0

3

7

1

0

2.8

Landline Average 0.04 0.0

Mobile to PSAP

Mobile Average 0.02 2.8

Destination Device	e 122		
Test (Configuration	Uplink Error Rate	Downlink Error
Rate		•	0
Mobile	to PSAP	0	0
Mobile	to PSAP	0	0
Mobile	to PSAP	0	1
Mobile	to PSAP	0	0
Mobile	to PSAP	0	0
Mobile	to PSAP	0	0
Mobile	to PSAP	0	4
Mobile	to PSAP	0	0
Mobile	e to PSAP		0
Mobile	e to PSAP	0	0
	to PSAP	0	0
	e to PSAP	0	0
		ice Under Test' = 122 (12 detail reco 0	rds) 0.42
Destination Devi	ce 123		
Test (Configuration	Uplink Error Rate	Downlink Error Rate
Mobile	to PSAP	0	0
Mobile	e to PSAP	0	0
Mobile	e to PSAP	0	8
Mobile	e to PSAP	0	0
Mobile	e to PSAP	0	0
Mobile	e to PSAP	0	0
Mobile	e to PSAP	0	5
Mobile	e to PSAP	0	0
Mobile	e to PSAP	o	0
		ice Under Test' = 123 (9 detail record 0	ds) 1.44
Destination Devi	ce 124		
Test	Configuration	Uplink Error Rate	Downlink Error Rate
Mobile	e to PSAP	0	0.62
Summ Avg	ary for 'Destination Devi	ce Under Test' = 124 (1 detail record 0	0.62

Destination Device 127

	Test Configuration	Uplink Error Rate	Downlink Error
Rate			٥
	Mobile to PSAP	3	0
	Mobile to PSAP	18	0
	Mobile to PSAP	13	0
	Mobile to PSAP	6	0
	Mobile to PSAP	4	0
	Mobile to PSAP	2	
	Mobile to PSAP	12	0
	Mobile to PSAP	3	0
	Mobile to PSAP	····· 7	0
	Mobile to PSAP	0	0
	Mobile to PSAP	0	11
	Mobile to PSAP	11	0
	Mobile to PSAP	0	0
	Mobile to PSAP	0	0
	Mobile to PSAP	0.32	30
	Mobile to PSAP	0	0
	Mobile to PSAP	0	0
	Mobile to PSAP	0.2	1.4
	Mobile to PSAP	0	0
	Mobile to PSAP	0	6
	Mobile to PSAP	0	0
	Mobile to PSAP	0	0
	Mobile to PSAP	O	0
	Mobile to PSAP	0	5
	Mobile to PSAP	0	0
	Mobile to PSAP	0	0
	Mobile to PSAP	5	0
	Mobile to PSAP	0	0
	Mobile to PSAP	5	0
	Mobile to PSAP	0	0
	Summary for 'Destination Device Avg	Under Test' = 127 (30 detail records) 2.98	1.78

Destination Device 136		
Test Configuration	Uplink Error Rate	Downlink Error Rate
Mobile to PSAP	0	0
Mobile to PSAP	0	0
Mobile to PSAP	2	0
Mobile to PSAP	0	0
Mobile to PSAP	0	0
Mobile to PSAP	1	0
Mobile to PSAP	1.55	1.3
Mobile to PSAP	1	0
Mobile to PSAP	0	0
Mobile to PSAP	0	0
Mobile to PSAP	5	8
Mobile to PSAP	3	0
Summary for 'Destination Devi Avg	ce Under Test' = 136 (12 detail record: 1.13	0.78
Destination Device 137		
Test Configuration	Uplink Error Rate Do	wnlink Error Rate
Mobile to PSAP	0	0
Mobile to PSAP	0	0
Mobile to PSAP	1	0
Mobile to PSAP	0	0
Mobile to PSAP	0	0
Mobile to PSAP	1	0
Summary for 'Destination Devi Avg	ice Under Test' = 137 (6 detail records 0.33	0.0
Destination Device 141		
Test Configuration	Uplink Error Rate Do	ownlink Error Rate
Mobile to PSAP	5	15
Summary for 'Destination Dev	ice Under Test' = 141 (1 detail record) 5	15
Destination Device 142		
Test Configuration	Ophini Elioi itate	ownlink Error Rate
Mobile to PSAP	0	10
Summary for 'Destination Devi Avg	ice Under Test' = 142 (1 detail record) 0	10

Destination Device 21

Test Configuration	Uplink Error Rate	Downlink Error Rate
Landline to PSAP	0	0
Landline to PSAP	0	0
Mobile to PSAP	0	0
Mobile to PSAP	0	0
Mobile to PSAP	0	0
Mobile to PSAP	0	0
Mobile to PSAP	0	0
Mobile to PSAP	0	0
Mobile to PSAP	0	0
Mobile to PSAP	0	0
Mobile to PSAP	0	0
Mobile to PSAP	0	0
Mobile to PSAP	0	0
Mobile to PSAP	0	0
Mobile to PSAP	0	0
Mobile to PSAP	0	0
Mobile to PSAP	0	0
Mobile to PSAP	0	0
Mobile to PSAP	0	0
Mobile to PSAP	0	0
Mobile to PSAP	0	0
Mobile to PSAP	0	0
Mobile to PSAP	0	0
Mobile to PSAP	0	0
Mobile to PSAP	0	0
Mobile to PSAP	0	0
Mobile to PSAP	2.58	0
Mobile to PSAP	1.27	0
Summary for 'Destination Device	Under Test' = 21 (28 detail record 0.14	rds) 0.0
Avg Landline Average	0.0	0.0
Mobile Average	0.15	0.0

Destination Device 99

Test Configuration	Uplink Error Rate	Downlink Er	ror Rate
Mobile to PSAP		0	0
Mobile to PSAP		0	0
Mobile to PSAP		0	0
Mobile to PSAP		0	0
Summary for 'Destination'	Device Under Test' = 99 (4 deta	il records) 0	0

